


How many fasteners do I need for my PegBoard X2®?

The quantity of fasteners needed depends on 2 things:

1. The size of the PegBoard to be mounted:
 - 2x2 unit requires minimum 9 total mounting points
 - 2x3 unit requires minimum 9 total mounting points
 - 2x4 unit requires minimum 12 total mounting points
 - 2x6 unit requires minimum 18 total mounting points
 - 2x8 unit requires minimum 24 total mounting points
 - 2x10 unit requires minimum 30 total mounting points
 - 3x4 unit requires minimum 16 total mounting points
 - 4x6 unit requires minimum 30 total mounting points
 - 4x8 unit requires minimum 35 total mounting points
 - 4x10 unit requires minimum 40 total mounting points
2. The number of structural wall components (ie wall studs) available for mounting
 - > try to position the PegBoard such that the maximum number of wall studs are utilized


Example #1

PegBoard size: 2x4
3 wall studs utilized
12 total mounting points required
● 9 screws
● 3 hollow wall anchors




Example #2

PegBoard size: 3x4
3 wall studs utilized
16 total mounting points required
● 12 screws
● 4 hollow wall anchors




Example #3

PegBoard size: 4x8
5 wall studs utilized
35 total mounting points required
● 25 screws
● 10 hollow wall anchors



● Fastening into wall stud



● Fastening into hollow wall

