

How many fasteners do I need for my PegBoard X2™?

The quantity of fasteners needed depends on 2 things:

- 1. The size of the PegBoard to be mounted:
 - 2x2 unit requires minimum 9 total mounting points
 - 2x3 unit requires minimum 9 total mounting points
 - 2x4 unit requires minimum 12 total mounting points
 - 2x6 unit requires minimum 18 total mounting points
 - 2x8 unit requires minimum 24 total mounting points
 - 2x10 unit requires minimum 30 total mounting points
 - 4x4 unit requires minimum 20 total mounting points
 4x6 unit requires minimum 30 total mounting points
 - 4x8 unit requires minimum 35 total mounting points
 - 4x10 unit requires minimum 40 total mounting points
- 2. The number of structural wall components (ie wall studs) available for mounting > try to position the PegBoard such that the maximum number of wall studs are utilized









